



THIS DRAWING IS CONFIDENTIAL AND IS SUPPLIED ON EXPRESS CONDITION THAT IT SHALL NOT BE LENT, COPIED OR DISCLOSED TO ANY OTHER PERSON OR USED FOR ANY OTHER PURPOSE WITHOUT WRITTEN CONSENT OF HARDIN MARINE INC.. BREACH OF THIS CONTRACT WILL HOLD ........ AND IT'S PRINCIPALS LIABLE FOR LOSS AND DAMAGES.

PART NO. HARDIN FOR GEN 4 SEA PUMPS: REPLACEMENT REBUILD KITS 11 Industry Dr. Palm Coast, FL 32137 MARINE 625-4100 386-445-2500 / FAX 386-445-1122 GEN 1: 625-4103 625-4173 MASTER REBUILD KIT TITI F: 625-4105 625-4179 IMPELLER KIT HARDIN GEN 4 SEA PUMP VERSIONS 625-4106 625-4107 **GEN 2:** www.hardin-marine.com 625-4109 625-4174 MASTER REBUILD KIT 625-4110 625-4189 IMPELLER KIT 625-4118

625-4178



-PIPE PLUG NOT USED IN GEN 2



FOR ALL HARDIN MERCURY GENERATION 4
REPLACMENT SEA PUMPS YOU CAN IDENTIFY
WHETHER YOU HAVE THE FIRST OR SECOND
VERSION OF THESE PUMPS BY SIMPLY
IDENTIFYING WHETHER YOUR PUMP HAS A
1/8"NPT BRASS DRAIN PLUG LOCATED ON THE
UNDERSIDE OF THE PUMP HOUSING BETWEEN
THE INLET/OUTLETS OF THE HOUSING, SEE FIG
A. IF THE HOUSING IS OFF THE PUMP GEN 1
HAD A SLOT IN THE BODY. SEE FIG B.

GEN 1 UP TO 12/2012 GEN 2 01/2013 AND UP -NO TAB USED IN GEN 2