
HARDIN MARINE 11 Industry Dr. Palm Coast, FL 32137 386-445-2500 / FAX 386-445-1122

DESCRIPTION:

MERCURY SEA PUMP REBUILD KIT - GEN 2

PART NO.: 625-4178



IINSTALLATION INSTRUCTIONS:

1) INSTALL WEAR PLATE (C)INTO BODY (A).
2) APPLY GREASE INSIDE BORE AREA.
INSERT IMPELLER (D) INTO BORE. MAKE
SURE IMPELLER BLADES ARE BENT IN THE
DIRECTION SEA PUMP WILL BE SPINNING.
THE BACK SIDE OF BODY SHOWS
STANDARD LEFT HAND ROTATION.
3) INSTALL LARGER O-RING (B) IN THE ORING GROOVE IN BODY. APPLY A LIGHT
COAT OF GREASE TO O-RING. THIS WILL
HOLD O-RING IN PLACE.

- 4) INSTALL SMALL O-RING (F) INTO THE GROOVE IN YOUR STOCK MERCURY BEARING HOUSING. APPLY LIGHT COAT OF GREASE TO O-RING. THIS WILL HOLD O-RING IN PLACE.
- 5) SLIDE WEAR PLATE (E) OVER YOUR STOCK MERCURY SHAFT AND AGAINST THE BEARING HOUSING.
- 6) INSERT MERCURY SHAFT AND BEARING HOUSING ONTO SEA PUMP BODY ASSEMBLY.
- 7) APPLY ANTI-SEIZE TO THE THREADS OF THE SUPPLIED BOLTS. MAKE SURE TO USE THE LONG BOLTS IN THE SAME SPOT AS THE ORIGINAL BOLTS. THE LONG BOLTS ARE NEEDED TO ATTATCH YOUR SEA PUMP BRACKET.

OPTIONAL STAINLESS STEEL FITTINGS: 540-222151 1" NPT x 1-1/4 HOSE BARB, STRAIGHT 540-222161 1" NPT x 1-1/4 HOSE BARB, 45° 540-222173 1" NPT x 1-1/4 HOSE BARB, 90°

PART NO. **HARDIN** ITEM NO. PART NUMBER DESCRIPTION QTY. 11 Industry Dr. Palm Coast, FL 32137 MARINE 625-4178 386-445-2500 / FAX 386-445-1122 625-1026 O-RING 1 TITLE: SEA PUMP REBUILD KIT 625-4018 2 WEAR PLATE, SEA PUMP 1 3 625-1145 O-RING www.hardin-marine.com 4 625-4011 IMPELLER, SEA PUMP 5 625-4265 WEAR PLATE, INTERNAL 1 625-4063 6 BODY,2PC REPLACEMENT 7 90031AN-STSS WASHER, 5/16 AN 5 8 90031C350SHS BOLT - SHCS - 5/16-18x3.50 4 9 90031C275SHS BOLT - SHCS - 5/16-18x2.75 1 8 6 5

THIS DRAWING IS CONFIDENTIAL AND IS SUPPLIED ON EXPRESS CONDITION THAT IT SHALL NOT BE LENT, COPIED OR DISCLOSED TO ANY OTHER PERSON OR USED FOR ANY OTHER PURPOSE WITHOUT WRITTEN CONSENT OF HARDIN MARINE INC.. BREACH OF THIS CONTRACT WILL HOLD AND IT'S PRINCIPALS LIABLE FOR LOSS AND DAMAGES.